

Firmware Version: UV25Pro_NRF_401+_V0.20_250217.kdhx

Update Tool: Baofeng Bootloader Pro

Change Log:

UV-25 Plus: Fixed the bug that the GPS radar image does not show the distance to teammates after sharing the location.

Warning:

Do not update the firmware if your radio is functioning properly.

Update steps:

1. Install the update tool “Baofeng Bootloader Pro”
- 2 .Open the “Baofeng Bootloader Pro”
- 3.Select the firmware “UV25Pro_NRF_401+_V0.20_250217.kdhx”
- 4.Choose the COM port
5. Press and hold SK2 and SK3 (the two buttons below PTT), then turn on the radio, and the status indicator lights up green. Then connect to the programming cable
6. Select the “Manual update” [手动升级]
- 7 . Reset the radio via Menu 27

Please refer to the picture below to update the firmware:

